


## 17 Construction of external corner



### Attention!

Mullion and transom processing as described above.  
 Corner construction not suitable for sloping roofs!  
 The transoms have to be screwed as a principle!

figure 17.1

## 17.1 Construction of internal corner




figure 17.2

### Attention!

Corner construction not suitable for sloping roofs! The transoms have to be screwed as a principle!